

## **2004 - 2009 Cadillac XLR: Service Information: #PIC4693B: Navigation Radio Clock Inaccurate By 1 Hour**

**#PIC4693B: Navigation Radio Clock Inaccurate By 1 Hour - keywords 1 hour clock display fast gps hour jump move moves navigation one radio - (Oct 10, 2008)**

**Subject:** Navigation Radio Clock Inaccurate By 1 Hour

**Models:** 2004-2009 Cadillac XLR models

---

This PI was superseded to add 2009 model year. Please discard PIC4693A.

---

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### **Condition/Concern:**

Some customers may comment that the clock on the Navigation Radio is inaccurate by 1 hour. This may be due to a concern within the Navigation Radio.

### **Recommendation/Instructions:**

Currently, the only known repair is to set the clock to "GPS Time". This can be accomplished by selecting the "Clock Adjust Screen" and then press the "GPS Time" button. Now the clock will update with

GPS time. Engineering is continuing to investigate this issue. This PI will be updated with the repair information once it becomes available.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

Online URL:

<https://www.xlr-net.com/knowledgebase/article/2004-2009-cadillac-xlr-service-information-pic4693b-navigation-radio-clock-inaccurate-by-1-hour-135.html>