

# 2007 - 2009 Cadillac XLR: Service Bulletin: 15682 Primary Tank Module Flange Fuel and Vapor Leaks

Special Coverage Adjustment

15682 Primary Tank Module Flange Fuel and Vapor Leaks

**Reference Number:** N150682

**Release Date:** August 2016

**GWM Number:** 2015682

**Revision:** 01

**Revision Description:** This bulletin is being revised to accurately depict the origin on the flange in which fuel and vapor leaks have been confirmed. Please discard all previous copies of bulletin 15682.

**Condition:** Some 2007 to 2009 model year Cadillac XLR and 2007 to 2013 model year Chevrolet Corvette vehicles may have a condition where a fuel odor is detected, fuel droplets appear below the left-hand fuel tank with fuel gauge level above 1/2, or a malfunction indicator lamp illuminates due to a leak path in the left-hand fuel pump module flange.

Service Bulletin attached below:

[15682-bulletin-1](#)

Online URL:

<https://www.xlr-net.com/knowledgebase/article/2007-2009-cadillac-xlr-service-bulletin-15682-primary-tank-module-flange-fuel-and-vapor-leaks-56.html>