


# **2004 - 2006 Cadillac XLR: Service Bulletin: Diagnostic Trouble Code (DTC) C0710 Steering Wheel Position Sensor (SWPS) Signal, Service Stability System Message on Driver Information Center (DIC)**



**Service Bulletin #:** 06-02-35-002

**Date:** January 2006

**Subject:** Diagnostic Trouble Code (DTC) C0710 Steering Wheel Position Sensor (SWPS) Signal, Service Stability System Message on Driver Information Center (DIC) (Inspect and Secure Wires in SWPS Connector)

**Model(s):**

2004 - 2006 Cadillac XLR

2005 - 2006 Chevrolet Corvette

with Steering Wheel -- Tilt, Telescoping (RPO N37)

Attached below is the PDF document for this service bulletin.

[06-02-35-002](#)

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a

General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

**© Copyright General Motors Corporation. All Rights Reserved**

Online URL:

<https://www.xlr-net.com/knowledgebase/article/2004-2006-cadillac-xlr-service-bulletin-diagnostic-trouble-code-dtc-c0710-steering-wheel-position-sensor-s-wps-signal-service-stability-system-message-on-driver-information-center-dic-95.html>